

AL-785 (FAA)

APP CRS	Rwy Idg	5286
264°	TDZE	533
	Apt Elev	545

RNAV (GPS) RWY 26
LACONIA MUNI (LCI)

T If local altimeter setting not received, use Concord altimeter setting and increase all MDAs 80 feet. DME/DME RNP-0.3 NA.


A Visibility reduction by helicopters NA.

MISSED APPROACH: Climb to 4400 direct TUYUC and hold, continue climb-in-hold to 4400.

AWOS-3
133.525

BOSTON APP CON
134.7 254.25

CLNC DEL
119.85

UNICOM
123.0 (CTAF) **L**

MISSED APCH FIX

Procedure NA for arrivals
at GRUMP via V496 NW Bnd
and V322 SW Bnd.

5 NM

TUYUC

ELEV 545


TDZE 533

CONCORD
CON


Procedure NA for arrivals
at CON VORTAC via V322
SW Bnd and V93 W Bnd.

MSA RW 20 25 NM

5600



REIL Rwy 26 **L**
HIRL Rwy 8-26 **L**



CATEGORY	A	B	C	D
LNAV MDA	1420-1¼	887 (900-1¼)	1420-2¾ 887 (900-2¾)	1420-3 887 (900-3)
CIRCLING	1420-1¼ 875 (900-1¼)	1600-1½ 1055 (1100-1½)	1600-3 1055 (1100-3)	2160-3 1615 (1700-3)

LACONIA, NEW HAMPSHIRE
Orig 11293

43°34'N-71°25'W

LACONIA MUNI (LCI)
RNAV (GPS) RWY 26

NE-1, 04 APR 2013 to 02 MAY 2013